UNCLASSIFIED

AD NUMBER AD462394 **NEW LIMITATION CHANGE** TO Approved for public release, distribution unlimited **FROM** Distribution authorized to U.S. Gov't. agencies only; Foreign Government Information; DEC 1964. Other requests shall be referred to British Embassy, 3100 Massachusetts Avenue, NW, Washington, DC 20008. **AUTHORITY** DSTL, ADM 227/2383, 19 Feb 2009

CULLILLERCHAL - IN - CONFIDENCE

TECHNICAL NOTE No......

NSTIC/0830 765

462394

OGED BY: **DD(** NO. **V** · FOR ELATIONS ONLY

MECHANICAL DEPARTMENT

ADMIRALTY ENGINEERING LABORATORY

WEST DRAYTON, MIDDLESEX

PRESSURE GAUGE TYPE TESTS - BUDENBERG GAUGE CO. LTD.

(PHOSPHOR-BRONZE TUBES)

The information is this document is disclosed in confidence to the recipient government on condition that it is not circulated outside government departments without the prior permission of the limistry of Defence (Navy Department).

2. The recipient is warned that information contained in this document may be subject to privately owned rights.



U.S. COM OUT THE PROPERTIONS ONLY

Copy No. 25

(5717) Wt. 27346/P.14552 2,500 10/62 P.I. Gp. 610

301BU.

A.E.L. TECHNICAL NOTE No. 1731.

DECEMBER, 1964.

ADMIRALTY ENGINEERING LABORATORY WEST DRAYTON.

PRESSURE GAUGE TYPE TESTS - BUDENBERG GAUGE CO. LTD.

(PHOSPHOR-BRONZE TUBES)

Requests for permission to publish or disclose any of the material contained in this document and any enquiries concerning its contents should be addressed to: Director of Marine Engineering, Ministry of Dofence, Bath.

This document is issued by Superintendent, Admiralty Engineering Laboratory, and the views expressed in it are not necessarily those of the Director of Markae Engineering, Ministry of Defence, Bath. Any conclusions or opinions are to be regarded as being of an interim nature and may be subject to revision after further investigation.

ii

SUMMARY

Two 4" gauges, one surface mounting, 0-200 p.s.i. for use with Oxygen, and one flush mounting, 0-600 p.s.i., were resubmitted by Budenberg Gauge Co.Ltd. for type test approval in accordance with ADSPEC.1001A. The Oxygen gauge met all the specified requirement, except for two minor points in construction. The other gauge failed the shock tests in that physical damage occurred during these tests.

i.i.i

A.E.L. TECHNICAL NOTE No.1731.

DECEMBER, 1964.

DISTRIBUTION

			Copy No.
4 copies	-	A.E.L. (internal use)	1 –4-
1 copy	-	Ship Dept. Library, Bath.	5
3 copies	-	D.G. Ships, D.M.E., Bath. (1 copy Attn. Cdr. L.I. Wills, R.N. XEIV/130.) (2 copies Attn. Section XEIV/130)	6 7&8
24 copies	-	N.S.T.I.C. Report Section/R.D.S.D.(N) for distribution to: C.B.N.S 2 copies U.S.N.A 5 copies U.S.O.N.R.(L) - 1 copy U.S.J.S.R.P 2 copies S.(T).C. Ottawa - 1 copy N.T.L.O. Australia - 1 copy	9 - 32
1 сору	-	C.R.N.S.S.	33

A.E.L. TECHNICAL NOTE No

DECEMBER

CONTENTS

									Paragr
INTRODUCTION	٠.	•		•	•			•	1
TEST PROCEDURE	•		•	•	•	•			5 .
TEST RESULTS	•		•	•	•		•	•	7
CONCLUSIONS	•	•	•	•	•	•	•	•	10

FIGURES 1 - 4.

A.E.L. TECHNICAL NOTE No. 1731.

DECEMBER, 1964.

ADMIRALTY ENGINEERING LABORATORY WEST DRAYTON.

PRESSURE GAUGE TYPE TESTS - BUDENBERG GAUGE CO.LTD. (PHOSPHOR-BRONZE TUBES)

INTRODUCTION

- 1. Two 4" gauges, one surface mounting, 0-200 p.s.i. range for use with Oxygen, and one flush mounting, 0-600 p.s.i. range, were resubmitted for type test approval in accordance with ADSPEC. 1001Λ .
- 2. Beryllium copper bourdon tubes are fitted as standard to gauges of this type and size at present supplied by this firm. The gauges reported upon herein are fitted with phosphor bronze tubes.
- 5. The Oxygen gauge as originally received, with an orifice check in the inlet connection, would not respond to pressure, even with the orifice check removed. Whatever caused the restriction was corrected by the makers and the gauge returned without the orifice check for testing.
- 4. Tests were conducted between 26th September and 8th December, 1964, under A.E.L., R & D Programme, Work Item No.406/1.

TEST PROCEDURE

- 5. Each gauge was examined and then tested for accuracy at the various stages of the type tests as detailed in ADSPEC. 1001A. up to the point when physical damage occurred.
- 6. A Budenberg dead weight tester was used to carry out the accuracy tests.

TEST RESULTS

- 7. These are displayed graphically in Figs. 1 and 2, which also include inspection remarks.
- 8. The straight line boundaries on each graph indicate the specified limits of error for the relevant accuracy test.
- 9. Damage to the flush mounting, 0-600 p.s.i. range gauge that occurred during the shock tests is shown in Figs. 3 and 4.

CONCLUSIONS

10. The surface mounting, 0 - 600 p.s.i., Oxygen gauge withstood all tests and its accuracy throughout remained within the specified limits, but it did not meet the specification in two relatively minor points. Although with the distance pieces assembled the fixing holes are the correct diameter it is considered that the 5/16" diameter holes on the specified P.C.D. in the mounting flange excessively weakens the flange. The minimum thickness of metal between the holes and the outside diameter of the flange is less than 1/16".

/ The f.dspec


- 2 -

The Adspec does not favour the use of plastic material for the back plate, but it withstood the shock tests without damage.


11. The flush mounting, 0-600 p.s.i., gauge failed to meet the specified requirements, in that physical damage occurred during the shock tests. It is recommended that future submissions should not include any fitments restricting free movement of the bourdon tube during testing. Also, if countersunk securing holes are required in the aluminium back plate its thickness should be increased.


Experimental Work by - G.C.J. HARNER, (Senior D'man.)


Head of Section - M. RICHARDS, (Commander, R.N.)











S SHOCK TEST het bedelgauge mounted vertically and connection

- Pointer Bent Suightly (see Fig. 3.).
47 Drop (Gauge Mounted Horizontally And Dial Facing Upwards. F BACK PLATE EXTRUDED OVER ONE OF ITS SECURING SCREWS (SEE FIG. 4) <u>Polititer on Pinion Hab Not Iocqurred as ear as Ean be iascertained</u> HAIRSPRING DISTORTED TO SOME EXTENT.

BOURDON TUBE END PIECE HAD CONTACTED BACK OF DIAL AND BRASS STOP:

SEE FIG. 3) SECURED TO BACK PLATE IN WAY OF TUBE END PIECE. FORCE ON STOP CAUSED EXTRUSION OF BACK PLATE

4 INSPECTION REMARKS

GAUGE MEETS THE DIMENSIONAL AND MATERIAL REQUIREMENTS OF adspect tool (al., but the 22 sivis alluminum back plate is:: COMPARATIVELY WEAK AT THE COUNTERSUNK SECURING HOLES. THE BRASS STOP, FITTED PRESUMABLY TO PREVENT FREE MOVEMEN OF TUBE TOWARDS BACK PUATE WHEN UNDER VIBRATION IS CONSIDERED TO BE AN UNDESTRABLE ITEM ALTHOUGH FITTING OF SUCHTIEMS IS nat precuped in the specification 1:

COMMERCIAL - IN-CONFIDENCE.

A.E.L. TECHNICAL NOTE NO.1731,

FIG.3,





FIG.3. BUDENBERG, 4"(F), 0-600 p.s.i. GAUGE -DIAL INDICATING BENT POINTER AND ZERO ERROR AFTER SHOCK TESTS.

COMMERCIAL-IN-CONFIDENCE

A.E.L TECHNICAL NOTE NO.1731, FIG.4.



BUDENBERG, 4" (F), 0600 p.s. (. GAUGE - VIEW INDICATING DAMAGE TO BACK PLATE DURING SHOCK TESTS.

HG.A.

COMMERCIAL-IN-CONFIDENCE



dstl

Defense Technical Information Center (DTIC) 8725 John J. Kingman Road, Suit 0944 Fort Belvoir, VA 22060-6218 U.S.A.

AD#: AD462394

Date of Search: 19 February 2009

Record Summary: ADM 227/2383

Pressure gauge type tests: phosphor-bronze type tubes Former reference (Department): Note No. 1731 Held by The National Archives, Kew

This document is now available at the National Archives, Kew, Surrey, United Kingdom.

DTIC has checked the National Archives Catalogue website (http://www.nationalarchives.gov.uk) and found the document is available and releasable to the public.

Access to UK public records is governed by statute, namely the Public Records Act, 1958, and the Public Records Act, 1967.

The document has been released under the 30 year rule.

(The vast majority of records selected for permanent preservation are made available to the public when they are 30 years old. This is commonly referred to as the 30 year rule and was established by the Public Records Act of 1967).

This document may be treated as **UNLIMITED**.